FACILITY: COLLIDER ACCELERATOR DEPARTMENT

CHAPTER: XII "OPERATIONS TURNOVER"

GUIDELINE	PERFORMANCE	EXCEPTIONS
Turnover Checklists a) Checklists should document that the following	Turnover Checklists a) Checklists document many parameters that are reviewed after a specific	Turnover Checklists None
have been reviewed:	evolution (see <u>Keyword=Check</u>). These checklists generally relate to turnover of a system for routine operations as opposed to shift turnover:	TVOIC
 Equipment checklists showing status, and noting any abnormal lineups or valid alarms 	i) Equipment checklists showing status, and noting any abnormal lineups or valid alarms; for example, see OPM 4.56.a , "AGS Ring Sweep Checklist"	
ii) Round sheets and logs	ii) Round sheets and logs; for example, see OPM 4.1.f , "C-A Gate Security Log Sheet for Remote Access"	
iii) Operator checklists providing vital information on key operational and safety parameters	iii) Operator checklists providing vital information on key operational and safety parameters; for example, see OPM 9.1.2 , "Procedure for Preparing and Maintaining an RSC Check-Off List and Assuring that RSC Recommendations are Completed"	
iv) Operations Supervisory Checklists showing facility status, planned maintenance, and tests	iv) Operations supervisory checklists showing facility status, planned maintenance, and tests; for example, see OPM 2.27.a , "Operations Acceptance of New Equipment/Systems Checklist"	
2) Document Review	2) Document Review	2) Document Review
A review of documents and checklists, as required, should be made to ensure that the operators review and understand the important operations history, the present status of the equipment, and any planned events.	 a) Shift turnovers include a thorough review of appropriate documents describing important aspects of accelerator status, and some shift turnovers may include a review of a checklist if relevant to operations or ESH. Reviews are complimented by a discussion between the off-going and oncoming operators. For example, see OPM 2.8, "Shift Turnover" and OPM 7.1.1, "Cryogenic Operations Shift Turnover." 	None
Control Panel Walkdown Walkdown the control panels to determine the plant's status by observing system lineups, switch positions, lighted annunciators, chart recorders, and status lights	3) Control Panel Walkdown a) Shift turnovers include a thorough inspection of equipment, control systems and appropriate accelerator instrumentation. See OPM 2.8, "Shift Turnover" and OPM 7.1.1, "Cryogenic Operations Shift Turnover."	3) Control Panel Walkdown None
b) Oncoming and outgoing personnel should review control panels together.	b) Reviews are complemented by a discussion between the off-going and oncoming operators. See OPM 2.8 , "Shift Turnover" and OPM 7.1.1 , "Cryogenic Operations Shift Turnover."	

DATE: 1/2/03

PAGE: 1 of 2

FACILITY: COLLIDER ACCELERATOR DEPARTMENT

CHAPTER: XII "OPERATIONS TURNOVER"

PAGE: 2 of 2

DATE: 1/2/03

GUIDELINE	PE	ERFORM	MANCE	EXCEPTIONS
that the oncoming pe cognizant of plant co are stable, the oncom supervisor should sta	personnel are confident rsonnel are fully inditions, and conditions ing operators and	a) 7 f	The oncoming Operations Coordinator signifies that he/she is cognizant of facility operations and is prepared to assume responsibility for operations at the end of the previous shift. See OPM 2.8 , "Shift Turnover" and OPM 7.1.1 , "Cryogenic Operations Shift Turnover."	4) Discussion and Exchange of Responsibility None
required, should be c Operations Superviso	and support groups, as onducted by the or and include a review of aipment problems, and	a) A	Crew Briefing Any special information required on a particular shift is written in the logbook by the senior person in charge of the group and verbally emphasized during briefings with operators. See OPM 2.8 , "Shift Turnover" and OPM 7.1.1 , "Cryogenic Operations Shift Turnover."	5) Shift Crew Briefing None
Reliefs Occurring During a) Relief reviews and w performed as require	the Shift 6 alkdowns should be	a) l a c l	efs Occurring During the Shift Exchange of operators or the Operation Coordinator during a shift is done in a way to ensure that the oncoming person is knowledgeable of the conditions as he would have been had a complete shift turnover process been conducted. See OPM 2.8 , "Shift Turnover" and OPM 7.1.1 , "Cryogenic Operations Shift Turnover."	6) Reliefs Occurring During the Shift None